YEAR: 2015 MAKE: HYUNDAL MODEL: Santa Fe WO #: 65634 UNIT: 231062 COLOUR: Grey ENGINE SIZE: 201 # OF CYL: 4 TRANSMISSION: D STD D AUTO # OF SPEEDS 6 CVT TRANSMISSION D						
SERVICEABLE N/A KM 143,556 SERIAL #5X42UDLA9FGQ92600 BRAKES: D'ABS D NO ABS						
ELECTRICAL	HEADLIGHTS SIGNAL LIGHTS PARK LIGHTS HORN LICENSE LIGHT BRAKE LIGHTS WIPERS AND WASHERS	BACK UP LIGHTS TAIL LIGHTS HAZARD SIGNALS BATTERY ENDS / CABLES ALTERNATOR OUTPUT (AMPS) BATTERY LOAD TEST STARTER DRAW (AMPS) BATTERY LOAD TEST STARTER DRAW (AMPS)				
UNDER	BELTS/TENSION BLOCK HEATER COOLANT STRENGTH	MOTOR OIL CONDITION OIL LEAKS COOLANT LEAKS				
TIRES	LEFT FRONT	RIGHT FRONT 0 % WORN 16 PSI 35 RIGHT REAR 0 % WORN 16 PSI 35 TIRE SIZE 1555 R 19 H				
DRIVE	DRIVE TRAIN NOISE VIBRATION IN DRIVE	ENGINE MOUNTS O				
TRANSMISSION	TRANY SYNCHROMESH (STD)	TRANS AXLE LEAKS TRANSFER CASE A/TRANS SHIFT POINTS FRONT/REAR DIFFERENTIAL E				
EXHAUST	CROSSOVER PIPE FRONT PIPE(S) TAIL PIPE(S) EXTENSION PIPE	MUFFLERS: HANGERS INTERMEDIATE PIPE CATALYTIC CONVERTER				
BRAKES	ABS OPERATION	WHEEL CYLINDERS WHEEL BEARINGS MASTER CYLINDER HAND BRAKE OPERATION CALIPERS WHEEL CYLINDERS T CALIPERS O				
STEERING & SUSPENSION	STABILZER LINKS TIE ROD ENDS INNER SPRINGS FRONT TIE ROD ENDS OUTER SHOCKS FRONT OR STRUTS LOWER CONTROL ARM BUSHING SHOCKS REAR OR STRUTS ALIGNMENT 2W OR 4W TIE ROD ENDS INNER SHOCKS FRONT OR STRUTS LOWER CONTROL ARM BUSHING STEERING (RACK) HYD/FIGOTIC POWER STEERING LEAKS TIE ROD ENDS INNER SHOCKS FRONT OR STRUTS CONTROL ARM BUSHING STEERING (RACK) HYD/FIGOTIC TO STRUTS TO STEERING (RACK) HYD/FIGOTIC TO STRUTS TO STEERING (RACK) HYD/FIGOTIC TO STRUTS SHOCKS FRONT OR STRUTS SHOCKS REAR OR STRUTS TO STEERING (RACK) HYD/FIGOTIC TO STRUTS SHOCKS REAR OR STRUTS STEERING (RACK) HYD/FIGOTIC TO STRUTS SHOCKS REAR OR STRUTS TO STRUTS SHOCKS REAR OR STRUTS STEERING (RACK) HYD/FIGOTIC TO STRUTS SHOCKS REAR OR STRUTS					
DASH	SPEEDO/ODOMETER (OP ONLY NOT ACCURACY) REAR DEFROST (IF COLD ENOUGH)	HEATER/DEFROST CONTROLS DI GAUGE/ACCS LITES/INTERIOR LITES RADIO/ANTENNA				
INTERIOR	POWER MANUAL SEAT	780-466-8244 BBB E				
	Ma Ja	mes				

MOTORS



Best Choice Automotive

"YOUR NEW CAR MAINTENANCE SPECIALIST"

Best Choice Automotive, 9928 - 35 Avenue N.W. Edmonton, AB. T6E 6B2, Canada Phone: (780) 466-8244 Fax: (780) 435-1636 email: bcauto@telusplanet.com Website:www.bestchoiceautomotiveltd.com

Invoice

Bill To Mac James Motors Motors, Mac James 9111 34A Avenue Edmonton, ALBERTA T6E 5T6

Canada

Business (780) 439-2277 south Fax (780) 433-5534 south Email sales@macjames.ca

Invoice # 61813 Work Order # 65634 Service Advisor 04 Technician 14

Plate AB 231062

Description grey 2015 Hyundai Santa Fe Sport 2.0T L4 2.0L

1998CC 122CID VIN A VIN 5XYZUDLA9FG292600

Unit 231062 Odometer 143,556

Invoice Date 3/14/2023 9:05 AM Appointment 3/9/2023 10:04 AM Promised 3/9/2023 5:00 PM

ervice			
Vehicle Inspection			*400.00+0
Labor	1 Hour		\$109.00 *G
		Sub	\$109.00
Scan For Codes			
Labor	0.6 Hour		\$60.00 *G
		Sub	\$60.00
Replace Oil & Filter			
Labor	0.3 Hour		\$29.00 *G
5w30 Synthetic BULK	5 Unit	\$11.89 / Unit	\$59.45 EG
Engine Oil Filter	1 Unit	\$8.62 / Unit	\$8.62 G
		Sub	\$97.07
Replace wiper blades			
Labor	0.2 Hour		\$20.00 *G
blade	1 Unit	\$16.67 / Unit	\$16.67 G
wiper blade	1 Unit	\$23.15 / Unit	\$23.15 G
WIPER BLADES	1 Unit	\$12.95 / Unit	\$12.95 G
		Sub	\$72.77
Mount, Install & Balance 4 New Tire(s)			
Labor	1 Hour		\$109.00 G
Tire	4 Unit	\$276.67 / Unit	\$1,106.68 GT
		Sub	\$1,215.68
Disc Brake Pads & Rotors (Rear)			
Labor	1.4 Hour		\$152.60 *G
Disc Brake Pad	1 Unit	\$117.84 / Unit	\$117.84 G
Disc Brake Rotor	2 Unit	\$82.82 / Unit	\$165.64 G
		Sub	\$436.08
Replace 2 lower Suspension Ball Joints	WAY YORK A		
Labor	1.4 Hour	State of the second second second second	\$152.60 *G
ball joint	2 Unit	\$117.38 / Unit _	\$234.76 G
		Sub	\$387.36
Total Parts			\$1,745.76
Total Labor		_	\$632.20
Total Before Taxes & Miscellaneous Charges			\$2,377.96
27/2023 3:54 PM Inv	roice #61813		Page 1

(*) Shop Supplies*
(E) Environmental Compliance Fees*
(G) Canadian Goods and Services Tax (GST#) R138358932 R0001
(T1) Provincial Tire Stewardship Fee (P/LT)
Grand Total

\$25.00 PG \$5.00 G \$120.95 \$16.00 PG1 \$2,544.91

Mac James Motors charged \$2,544.91 to Account - 1 - Mac James Motors - Net 30 Days

WHEEL NUTS MUST BE RETORQUED BETWEEN 80-100KM FROM INVOICE DATE

INSPECTION FEES (Minium 1/2 hour) apply unless work performed at time of inspection. MAY be waived upon completion of work performed.

WHEEL NUTS MUST BE RE-TORQUED WITHIN 80 to 100 KMS

	THANK YOU!	We appreciate your bu	siness
Signature :	Signature :		