YEA	R:	OLA MAKE: FORO MODE	EL: ESCAI	P12 WO #: 67 6/6 UNIT 24 100 BCOLOUR: G PR	P					
-			MISSION: ST	TD 🗗 AUTO # OF SPEEDS CVT TRANSMISSION (<u></u>					
SERVICEABLE N/A KM 145960 SERIAL # FMC4969 HUB 24696 BRAKES: ABS INO ABS										
ELECTRICAL	विवय्वय्वय	HEADLIGHTS SIGNAL LIGHTS PARK LIGHTS HORN LICENSE LIGHT BRAKE LIGHTS WIPERS AND WASHERS	BLAORS	BACK UP LIGHTS TAIL LIGHTS HAZARD SIGNALS BATTERY ENDS / CABLES ALTERNATOR OUTPUT (AMPS) BATTERY LOAD TEST STARTER DRAW (AMPS)						
UNDER	400	BELTS/TENSION BLOCK HEATER COOLANT STRENGTH	40	MOTOR OIL CONDITION OIL LEAKS COOLANT LEAKS						
TIRES	4	- 1	PSI <u>New</u> PSI <u>NUW</u>	RIGHT FRONTHUNG WORN 39 PSI NEW RIGHT REAR NEW WORN 30 PSI NEW C TIRE SIZE 239/55 217						
DRIVE		DRIVE TRAIN NOISE VIBRATION IN DRIVE		CV JOINTS + BOOTS ENGINE MOUNTS)					
TRANSMISSION	THE WAY	CLUTCH LINKAGE/LEAKS TRANY OIL CONDITION TRANY SYNCHROMESH (STD)		TRANS AXLE LEAKS TRANSFER CASE A/TRANS SHIFT POINTS FRONT/REAR DIFFERENTIAL	k F					
EXHAUST	MODE	CROSSOVER PIPE FRONT PIPE(S) TAIL PIPE(S) EXTENSION PIPE		MUFFLERS HANGERS INTERMEDIATE PIPE CATALYTIC CONVERTER						
BRAKES	मिन्न पन	ABS OPERATION LINING OR PADS FRONT % WO LINING OR PADS REAR BRAKE LINES AND CABLES BRAKE HOSES	DRN	WHEEL CYLINDERS WHEEL BEARINGS MASTER CYLINDER HAND BRAKE OPERATION CALIPERS U WHEEL CYLINDER T CALIPERS						
STEERING & SUSPENSION	9999	SPRINGS FRONT SPRING REAR								
DASH		SPEEDO/ODOMETER (OP ONLY NOT ACCURACY) REAR DEFROST (IF COLD ENOUGH)		HEATER/DEFROST CONTROLS BAUGE/ACCS LITES/INTERIOR LITES RADIO/ANTENNA						
INTERIOR	0000	INTERIOR TRIM POWER WINDOWS/MANUAL WINDO POWER DOOR LOCKS/MANUAL LO		780-466-8244 BBB. TEST						
			Me Jen	nes Tors						



Best Choice Automotive

"YOUR NEW CAR MAINTENANCE SPECIALIST"

Best Choice Automotive, 9928 - 35 Avenue N.W. Edmonton, AB. T6E 6B2, Canada Phone: (780) 466-8244 Fax: (780) 435-1636 email: bcauto@telusplanet.com Website:www.bestchoiceautomotiveltd.com

Invoice

Bill To Mac James Motors Motors, Mac James 9111 34A Avenue Edmonton, ALBERTA T6E 5T6

Canada

Business (780) 439-2277 south Fax (780) 433-5534 south Email sales@macjames.ca

Invoice # 63120 Work Order # 67616 Service Advisor 05 Technician 14 Plate AB 241008

Description grey 2017 Ford Escape SE L4 2.0L 1999CC

122CID VIN 9

VIN 1FMCU9G99HUB24696

Unit 241008 Odometer 145,958

Invoice Date 11/6/2023 8:53 AM Appointment 10/31/2023 10:19 AM Promised 10/31/2023 5:00 PM

ervice			
Vehicle Inspection			
Labor			\$111.00 *G
		Sub	\$111.00
Replace Oil & Filter			
Labor			\$29.00 *G
5w30 Synthetic BULK	5 Unit	\$8.32 / Unit	\$41.60 EG
Engine Oil Filter	1 Unit	\$8.66 / Unit	\$8.66 G
		Sub	\$79.26
Replace wiper blades			
Labor			\$20.00 *G
blade	1 Unit	\$32.41 / Unit	\$32.41 G
blade	1 Unit	\$36.13 / Unit	\$36.13 G
blade	1 Unit	\$36.13 / Unit	\$36.13 G
		Sub	\$124.67
Replace lights			
Labor			\$24.00 *G
light module	1 Unit	\$277.79 / Unit	\$277.79 G
		Sub	\$301.79
Mount, Install & Balance 4 New Tire(s)			
Labor			\$111.00 G
Tire	4 Unit	\$197.53 / Unit	\$790.12 GT
wheel nut	20 Unit	\$4.84 / Unit	\$96.80 G
No.		Sub	\$997.92
Please Note: Wheels require lug nut re-torque.			
whools require tag that re-torque.			
Alignment, Four Wheel			
Labor		100 PC 100 PC	\$147.00 *G
		Sub	\$147.00
eft Inner Steering Tie Rod end			
Remove and Replace components as required to access and install materials Labor			¢166 50 *C
Steering Tie Rod	1 Unit	\$85.00 / Unit	\$166.50 *G \$85.00 G
Steeling He float	1 UIIIL		
		Sub	\$251.50

Total Parts Total Labor Total Before Taxes & Miscellaneous Charges	\$1,404.64 \$608.50 \$2,013.14
(*) Shop Supplies* (E) Environmental Compliance Fees* (G) Canadian Goods and Services Tax (GST#) R138358932 R0001 (T1) Provincial Tire Stewardship Fee (P/LT) Grand Total	\$25.00 PG \$5.00 G \$102.71 \$16.00 PG1 \$2,161.85

Mac James Motors charged \$2,161.85 to Account - 1 - Mac James Motors - Net 30 Days

WHEEL NUTS MUST BE RETORQUED BETWEEN 80-100KM FROM INVOICE DATE

INSPECTION FEES (Minium 1/2 hour) apply unless work performed at time of inspection. MAY be waived upon completion of work performed.

WHEEL NUTS MUST BE RE-TORQUED WITHIN 80 to 100 KMS

THANK YOU! We	e appreciate your business	
Signature :		

11/6/2023 8:54 AM