

YEAR: 2016 MAKE: VW MODEL: Tiguan WO #: 65344 UNIT: 231041 COLOUR: White
ENGINE SIZE: 2.0 # OF CYL: 4 TRANSMISSION: ☐ STD ☒ AUTO # OF SPEEDS 6 CVT TRANSMISSION ☐
☒ SERVICEABLE ☐ N/A KM 110642 SERIAL # WVGJV7AX86W63173 BRAKES: ☒ ABS ☐ NO ABS

ELECTRICAL	☒ HEADLIGHTS	_____	☒ BACK UP LIGHTS	_____
	☒ SIGNAL LIGHTS	_____	☒ TAIL LIGHTS	_____
	☒ PARK LIGHTS	_____	☒ HAZARD SIGNALS	_____
	☒ HORN	_____	☒ BATTERY ENDS / CABLES	_____
	☒ LICENSE LIGHT	_____	☒ ALTERNATOR OUTPUT (AMPS)	_____
	☒ BRAKE LIGHTS	_____	☒ BATTERY LOAD TEST	_____
UNDER HOOD	☒ WIPERS AND WASHERS	_____	☒ STARTER DRAW (AMPS)	_____
	☒ BELTS/TENSION	_____	☒ MOTOR OIL CONDITION	_____
TIRES	☒ BLOCK HEATER	_____	☒ OIL LEAKS	_____
	☒ COOLANT STRENGTH	<u>-50°C</u>	☒ COOLANT LEAKS	_____
	☒ LEFT FRONT <u>10</u> % WORN _____ PSI <u>40</u>	☒ RIGHT FRONT <u>10</u> % WORN _____ PSI <u>40</u>		
DRIVE LINE	☒ LEFT REAR <u>25</u> % WORN _____ PSI <u>40</u>	☒ RIGHT REAR <u>25</u> % WORN _____ PSI <u>40</u>		
	☒ SPARE <u>0</u> % WORN _____ PSI <u>60</u>	☒ TIRE SIZE _____		
TRANSMISSION	☒ DRIVE TRAIN NOISE	_____	☒ CV JOINTS + BOOTS	_____
	☒ VIBRATION IN DRIVE	_____	☒ ENGINE MOUNTS	_____
EXHAUST	☒ AWD / FWD / 4WD	_____	☒ TRANS AXLE LEAKS	_____
	☒ CLUTCH LINKAGE/LEAKS	_____	☒ TRANSFER CASE	_____
BRAKES	☒ TRANX OIL CONDITION	_____	☒ A/TRANS SHIFT POINTS	_____
	☒ TRANX SYNCHROMESH (STD)	_____	☒ FRONT / REAR DIFFERENTIAL	_____
STEERING & SUSPENSION	☒ CROSSOVER PIPE	_____	☒ MUFFLERS	_____
	☒ FRONT PIPE(S)	_____	☒ HANGERS	_____
DASH	☒ TAIL PIPE(S)	_____	☒ INTERMEDIATE PIPE	_____
	☒ EXTENSION PIPE	_____	☒ CATALYTIC CONVERTER	_____
INTERIOR	☒ ABS OPERATION	_____	☒ WHEEL CYLINDERS	_____
	☒ LINING OR PADS FRONT <u>0</u> % WORN <u>NEW</u>	☒ WHEEL BEARINGS	_____	
ROAD TEST	☒ LINING OR PADS REAR <u>20</u> % WORN	☒ MASTER CYLINDER	_____	
	☒ BRAKE LINES AND CABLES	☒ HAND BRAKE OPERATION	_____	
POWER WINDOWS/MANUAL WINDOWS	☒ BRAKE HOSES	☒ CALIPERS	_____	
	☒ STABILIZER LINKS	☒ TIE ROD ENDS INNER	☒ BALL JOINTS LOWER	
POWER DOOR LOCKS/MANUAL LOCKS	☒ SPRINGS FRONT	☒ TIE ROD ENDS OUTER	☒ SHOCKS FRONT OR STRUTS	
	☒ SPRING REAR	☒ LOWER CONTROL ARM BUSHING	☒ SHOCKS REAR OR STRUTS	
POWER/MANUAL SEAT	☒ ALIGNMENT 2W OR 4W	☒ POWER STEERING LEAKS	☒ STEERING (RACK) HYD/Electric <u>Electric</u>	
	☒ SPEEDO/ODOMETER (OP ONLY NOT ACCURACY)	☒ HEATER/DEFROST CONTROLS	_____	
ROAD TEST	☒ REAR DEFROST (IF COLD ENOUGH)	☒ GAUGE/ACCS LITES/INTERIOR LITES	_____	
	☒ INTERIOR TRIM	☒ RADIO/ANTENNA	_____	
POWER/MANUAL SEAT	☒ POWER WINDOWS/MANUAL WINDOWS	☒ ROAD TEST	_____	
	☒ POWER DOOR LOCKS/MANUAL LOCKS	☒ ROAD TEST	_____	
POWER/MANUAL SEAT	☒ POWER/MANUAL SEAT	☒ ROAD TEST	_____	
	☒ POWER/MANUAL SEAT	☒ ROAD TEST	_____	

BEST CHOICE AUTOMOTIVE



780-466-8244





Best Choice Automotive

"YOUR NEW CAR MAINTENANCE SPECIALIST"

Best Choice Automotive, 9928 - 35 Avenue N.W. Edmonton, AB. T6E 6B2, Canada
Phone: (780) 466-8244 Fax: (780) 435-1636 email: bcauto@telusplanet.com
Website: www.bestchoiceautomotive.com

Invoice

Bill To Mac James Motors
Motors, Mac James
9111 34A Avenue
Edmonton, ALBERTA T6E 5T6
Canada

Business (780) 439-2277 south
Fax (780) 433-5534 south
Email sales@macjames.ca

Invoice # 61619
Work Order # 65344
Service Advisor 04
Technician 14

Plate AB 231041
Description White 2016 Volkswagen Tiguan S L4 2.0L
1984CC 121CID
VIN WVGJV7AX8GW613173
Unit 231041
Odometer 110,642

Invoice Date 1/27/2023 10:17 AM
Appointment 1/23/2023 10:13 AM
Promised 1/23/2023 5:00 PM

Service

Vehicle Inspection Labor

1 Hour		\$109.00 *G
	Sub	\$109.00

Replace Oil & Filter

Labor	0.3 Hour		\$29.00 *G
5w	5 Unit	\$15.98 / Unit	\$79.90 G
filter	1 Unit	\$25.40 / Unit	\$25.40 G
washer	1 Unit	\$0.76 / Unit	\$0.76 G
	Sub		\$135.06

Replace wiper blades

Labor	0.2 Hour		\$20.00 *G
blade	2 Unit	\$16.65 / Unit	\$33.30 G
rear wiper blade	1 Unit	\$18.32 / Unit	\$18.32 G
rear wiper arm	1 Unit	\$69.60 / Unit	\$69.60 G
	Sub		\$141.22

Disc Brake Pads & Rotors (Front)

Labor	1.2 Hour		\$130.80 *G
Disc Brake Pad	1 Unit	\$146.84 / Unit	\$146.84 G
Disc Brake Rotor	2 Unit	\$157.25 / Unit	\$314.50 G
	Sub		\$592.14

Replace Front Grille

grille 2-3days out	1 Unit	\$384.16 / Unit	\$384.16 G
Labor	1 Hour		\$109.00 *G
	Sub		\$493.16

Replace broken dash vents

Dash vent	2 Unit	\$171.36 / Unit	\$342.72 G
vent	1 Unit	\$185.92 / Unit	\$185.92 G
Labor	1 Hour		\$109.00 *G
	Sub		\$637.64

Battery - Replace

Battery	1 Unit	\$240.22 / Unit	\$240.22 G
Labor	0.3 Hour		\$30.00 *G
	Sub		\$270.22

Total Parts	\$1,841.64
Total Labor	\$536.80
Total Before Taxes & Miscellaneous Charges	<u>\$2,378.44</u>
(*) Shop Supplies*	
(E) Environmental Compliance Fees	\$25.00 PG
(G) Canadian Goods and Services Tax (GST#) R138358932 R0001	\$5.00
Grand Total	<u>\$120.17</u>
	\$2,528.61

Mac James Motors charged \$2,528.61 to Account - 1 - Mac James Motors - Net 30 Days

WHEEL NUTS MUST BE RETORQUED BETWEEN 80-100KM FROM INVOICE DATE

INSPECTION FEES (Minium 1/2 hour) apply unless work performed at time of inspection. MAY be waived upon completion of work performed.

WHEEL NUTS MUST BE RE-TORQUED WITHIN 80 to 100 KMS

THANK YOU! We appreciate your business

Signature : _____